

RECEIVED  
FEB 21 1990



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

6

OK 9467070059

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME

Wiley Post Airport

B. STREET (or other identifier)

5700 North Rockwell

C. CITY

Oklahoma City

D. STATE

OK

E. ZIP CODE

73107

F. COUNTY NAME

Oklahoma 109

G. OWNER/OPERATOR (if known)

1. NAME

2. TELEPHONE NUMBER

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL ☐ 2. STATE ☐ 3. COUNTY ☐ 4. MUNICIPAL ☐ 5. PRIVATE ☐ 6. UNKNOWN

I. SITE DESCRIPTION

Airport facility with 17 underground storage tanks.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

FI

K. DATE IDENTIFIED  
(mo., day, & yr.)

1/88

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

may be contaminating local ground water with lead.

SUPERFUND  
FILE

DEC 31 1991

REORGANIZED

M. PREPARER INFORMATION

1. NAME

Barbara Drosch

2. TELEPHONE NUMBER

055-6740

3. DATE (mo., day, & yr.)

2/16/90

9831299



Wiley Post Airport has a total of 17 underground storage tanks on-site for storing jet fuel (Ref. 25). The total combined capacities of these tanks is estimated to be 228,000 gallons. The tanks are between 2 and 28 years old (Ref. 25). It is not known whether any of these tanks have been leak tested. It is possible that Wiley Post Airport may also be contributing to the lead contamination of groundwater.

It is recommended that both Gulfstream Aerospace Corporation and Wiley Post Airport, which are upgradient of the City of Bethany wells, be investigated. In order to define the plume and source of groundwater contamination more accurately, it is recommended that those City of Bethany wells located nearest to Air Center be sampled. Furthermore, additional sampling of the on-site drainage ditch would assist in determining the extent of surface contamination.